



Infection Prevention and Control (IPAC) Lapse Report

Initial Report

Premise/facility under investigation:

LifeLabs Medical Laboratory Services

Address:

245 King St. W., Oshawa ON., L1J 2J7

Type of premise/facility: Medical Laboratory

IPAC Lapse Details

Date board of health became aware of potential IPAC lapse: 2024-08-30

Date IPAC lapse was linked to premise/facility: 2024-09-03

Date of initial report posting: 2024-09-12

How the potential IPAC lapse was identified: Complaint

Summary description of the IPAC lapse:

- No cleaning and disinfection of surfaces between clients.
- Client chair in poor repair.

IPAC Lapse Investigation

Did the IPAC lapse involve a member of a regulatory college? No

Were any corrective measures recommended and/or implemented? Yes

Please provide further details/steps:

- Ensure client contact surfaces are cleaned and disinfected between each client.
- Ensure surfaces, furnishings, equipment, and finishes are smooth, non-porous, seamless, and cleanable.

Date any order(s) or directive(s) were issued to the owner/operator:

2024-09-03

Initial Report Comments and Contact Information

Any additional comments: Operator education provided.

If you have any further questions, please contact the Durham Health Connection Line:

Telephone: 1-800-841-2729, or [email](#) us.